## **Hannah Elliott**

NOV 0.5 2021

**EXHIBIT** 

From:

Billie Johnson <windyacres26@gmail.com>

Sent:

Friday, November 5, 2021 5:23 PM

To: Cc:

Will VanVactor

Subject:

**PLANNING DEPT** Hannah Elliott

Re: exhibit for evidence on Vanier properity, that knife river believed their would be

problem at Woodward site before mining

Yes, it is. I just wanted to let it be known that Knife River must have been worried when they started mining the Woodward property six years ago. They drilled this well before anything happened, but are offering me a cistern that would have to have water carried in. How long would that take and why is it double standards in the water matter? Sincerely, Billie Johnson

On Fri, Nov 5, 2021 at 8:37 AM Will VanVactor < Will.VanVactor@co.crook.or.us> wrote:

Hi Billie,

The link isn't working. Is it a link to the same document you sent by separate email?

Will Van Vactor

**Director - Crook County Community Development** 

300 NE 3<sup>rd</sup> Street Room 12, Prineville, OR 97754

Office: (541) 447-3211

Website: www.co.crook.or.us

From: Billie Johnson <windyacres26@gmail.com>

To: Will VanVactor < Will.VanVactor@co.crook.or.us>

Sent: Thursday, November 4, 2021 4:37 PM

Subject: Re: exhibit for evidence on Vanier properity, that knife river believed their would be problem at Woodward

site before mining

## This was for evidence case #217-21-000436 Plng Preview attachment WELL LOG.pdfWELL LOG.pdf841 KB

On Thu, Nov 4, 2021 at 4:34 PM Billie Johnson < windyacres 26@gmail.com > wrote:

CONFIDENTIALITY NOTICE - This e-mail may contain information that is privileged, confidential, or otherwise exempt from disclosure under applicable law. If you are not the addressee or it appears from the context or otherwise that you have received this e-mail in error, please advise me immediately by reply e-mail, keep the contents confidential, and immediately delete the message and any attachments from your system.

| STATE OF OREGON CROO 54:   | WELL I.D. LABEL# L 121567   | Page 1 of 2  |
|--|---|--|
| WATER SUPPLY WELL REPORT   | START CARD # 1029875  | Tall Care  |
| (us required by ORS 537.765 & OAR 690-205-0210) 3/12   | /2016 ORIGINAL LOG#   | 112  |
| (1) LAND OWNER  First Name ### Adam   Kares   Last Name   MARSHAFE   MARSHAFE | (9) LOCATION OF WELL (legal description)  County CROOK Twp 14.00 S N/S Range 15.  Sec 23 NW 1/4 of the NE 1/4 Tax Lot  Tax Map Number 141 52300-00114 Lot  Lat " or 44.34805556  Long " or -120.89316667  Street address of well Nearest address  3992 NW STAHANCYK LIMINPRINEVILLE, OR   | .00 E E/W WN   |
| Material From To Amt sacks/lbs  Seat:  | (10) STATIC WATER LEVEL  Date SWL(psi)  Existing Well / Pre-Alteration  | 41 Jund 30.00  |
| 5) BORE HOLE CONSTRUCTION Special Standard (Attach conv  | 10 100 5110(p)  | a) + SWL(it)   |
| 5) BORE HOLE CONSTRUCTION Special Standard (Attach copy<br>Depth of Completed Well 281.00 ft.  | 30 32 20  | 30   |
| BORE HOLE   SEAL   Sacks/  | 3/11/2016 266 281 40  | 41   |
| 6 100 281 Calculated 2   |   | النظالا  |
|  | (11) WELL LOG Ground Flavetion 2024 00  |  |
|  | Otomic Licration 2734.00  |  |
| How was seal placed: MethodAB _XCDEXOther POURED DRY   | Material From   | To   |
| Backfill placed from ft. to ft. Material   | CLAY SILT BROWN 0 SAND BROWN 4  | 4  |
| Filter pack fromfl. tofl. Material Size  | Here was a service of   | 21   |
|  | SAND GRAVELS 21<br>SAND FINE BROWN 30   | 30<br>82   |
| Explosives used: Yes Type Amount   | SILT GRAY 82  | 88   |
| a) ABANDONMENT USING UNHYDRATED BENTONITE  | CLAY GRAY 88  | 266  |
| Proposed Amount Actual Amount  | GRAVELS FINE SAND BROKEN CLAYSTONE 266  |  |
| Casing Liner Dia + From To Gauge Stl Plstc Wld Thrd  Casing Liner Dia + From To Gauge Stl Plstc Wld Thrd  Shoe Inside X Outside Other Location of shoe(s) 281  Temp casing X yes Dia 10 From 0 To 98   | RECEIVED BY OWRD  MAY 1 7 2016  |  |
| PERFORATIONS/SCREENS Perforations Method   | SALEM, OR   |  |
| Screens Type Material Perf/ Casing/Screen Scry/stot Stot # of Tele/  | Date Started 3/8/2016 Completed 3/11/20   | )16  |
| Screen Liner Dia From To width length slots pipe size  | (unbonded) Water Well Constructor Certification   |  |
|  | his report was originally e-filed to this   |  |
|  |   |  |
|  | the original e-filed document is a  | attached.  |
|  | License Number 758 Date 3/12/2016   | The state of the s |
| WELL TESTS: Minimum testing time is 1 hour   | Date 3/12/2016  |  |
|  | Signed THOMAS R PECK (E-filed)  | Cart do  |
| Pump Bailer Air Flowing Artesian  Yield gal/min Drawdown Drill stem/Pump depth Duration (hr)  40 280 I  Temperature 57 °F Lab analysis Yes By  Water quality concerns? Yes (describe below) TDS amount 174 ppm From To Description Amount Units  | (bonded) Water Well Constructor Certification  I accept responsibility for the construction, deepening, alterative work performed on this well during the construction dates reporter during this time is in compliance with Oregon construction standards. This report is true to the best of my known License Number 1720  Date 3/12/2016 | rted above. All wor  |
| From To Description Amount Units   |   | 1 1 1  |
|  | Signed JACK ABBAS (E-filed)  Contact Info (optional)  |  |